

Pool Report November 2017

The pool air temperatures have been erratic for the past several weeks. Through my email conversations with Kurt I learned that a fan motor in the facility needs replacing and parts have been ordered. I have received no indication when they will arrive.

A request has been made to weather strip the bottom of the door between the vestibule and the main room. Cold air from this gap pours into the room.