

Pool Report - April 2017

The ambient temperature in the pool house has not been in the correct level of 88 degrees for several months. Kurt has made multiple calls to the pool service contractor to no avail. Finally last week a technician was sent out to trace the problem; it was learned that the thermostat was OK but there was a faulty connection between it and the heater.

For the past several days the air temperature has been between 84 and 85 degrees. The pool committee has requested that the air temperature be raised to 88 degrees.

Richard Miller